

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name:

Work Order Type: Weatherization

Audit Name: MADISON

CLIENT INFORMATION

Client Name:

Client ID:

Address:

Alt. Client ID: 16016SW-1142

AGENCY INFORMATION

Agency: SWHRA

Address: 1574 White AVE

Henderson, TN

Agency Contact: Oliver, Jerry

Agency Phone: (731) 989-5111

Fax:

Email Address:

Work Phone: Cell Phone: Email Address:

Company Name & License	e Number:
Contractor's Signature:	

COMMENT

NOTICE: CERTIFIED FIRM/ RENOVATOR REQUIRIED

All work performed and material must meet all requirements as stated in the Southeast Weatherization Field Guide. It is the contractor's responsibility to pull all necessary permits required for the town or county where the work is being performed. No change order work shall be done until the change order has been approved and signed. If heater is required no air sealing should be done before heater is installed

731-410-6797

Client Name:

Client ID:

Alt. Client ID: 16016SW-1142

Work Order (Bid Form)

Work Order Name / Report Run On: 5/28/2010 **DOE** Weatherization Assistant Version 8.5.0

Page 1 of 5

Measures

	Measure 1 Infiltration Redctn				Components				
(Comment				Estima	ted		Actual	
ş	Material / Labor	Description / Comment	Units	Qty	Unit Cos		1 (Qty Unit Co	
,	I Construction Materials/Hardwar e	Seal door to basement add threshold.Seal under kitchen sink. Seal crown molding in living room	Each	1					
2	Labor	Labor	Hour						
3	Construction Materials/Hardwar e	Seal off fireplace, Repair ceiling in living room arrox 5x3 area tape mud seams. Sal wall in hall behind bathtub	Each	1	and the second s	Transport			
4	Labor	Labor	Hour						
5	Construction Materials/Hardwar e	Seal pipes under bath vanity, Seal ceiling and corners in closet in empty bedroom	Each	1		A accommendation			
6	Labor	Labor	Hour		A 100 MIN (100 MIN (1				
7	Construction Materials/Hardwar e	Seal ceiling and corners in back bedroom closet, Seal where old attic fan was in hall	Each	1					
8	Labor	Labor	Hour						
9	Construction Materials/Hardwar e	Mastic duct boots	Each	1					To a series of the series of t
10	Labor	Labor	Hour						
C	Other Detail								
	and the second s					The state of the s			
Ĺ									
			A	leasure	Sub Total:	4 T C and 1 to . 4 to C and 2		Sub Total:	
	Field Notes:								

Client Name:

Client ID:

Alt. Client ID: 16016SW-1142

Work Order /Bid Form)

Work Order Name:

Report Run On: 5/28/2010

DOE Weatherization Assistant

Version 8.5.0 Page 2 of 5

(Measure 2 DW Comment	H Pipe Insulation			Componen	ts		ı	Inspected
					Estimated	•		Actual	I
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1					
2	Labor	Labor	Each	1					
(Other Detail								
				Measur	e Sub Total:	The latest and the la] .	Sub Total:	
	Measure 3 Attic	: Ins. R-30	a talahar saharan kalanda kala		Component				nspected
	omment	, ms. 11-50			Component	3 A I			
_					Estimated			Actual	L
¥	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Attic Insulation - Blown Cellulose -Add 10 inches	SqFt	558		ALL			
2	Labor	Labor	Hour	558		MINISTER STORY	To the contract of the contrac		
3	Construction Materials/Hardwar e	Install attic access cover	Each	1		AN AND AND AND AND AND AND AND AND AND A			
1	Labor	Labor	Hour					76	
0	ther Detail					A CONTRACTOR OF THE PARTY OF TH		Viene	THE STREET STREET, STR
							Price		
			A	//easure	Sub Total:		S	ub Total:	
A CONTRACTOR OF THE PROPERTY AND ADDRESS OF THE PROPERTY OF TH	Field Notes:								

Client Name: Client ID:

Alt. Client ID: 16016SW-1142

Work Order (Bid Form)

Work Order Name: Report Run On: 5/28/2010 DOE Weatherization Assistant Version 8.5.0

Page 3 of 5

Measure 4 D\ Comment	VH Tank Insulation			Componer	nts			Inspected
				Estimated	d l		Actual	1
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Hot Water Equipment	DHW Tank Insulation	Each	1		1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -			The state state of the state of
2 Labor	Labor	Each	1					****
Other Detail								
Account of the second of the s								
			Measur	e Sub Total:]	Sub Total:	
Measure 5 CO Comment	Monitor is Needed			Component Estimated				nspected
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Actual Unit Cost	Total
Health and Safety Items		Each	1		1000			Total
2 Labor	Labor	Hour	1					
Other Detail		parts to an annual state of the	,					
		Λ	leasure	Sub Total:		s	ub Total:	7.75
Field Notes:		**************************************		**************************************				

Client Name: Client ID:

Alt. Client ID: 16016SW-1142

Work Order (Bid Form)

Work Order Name:

Report Run On: 5/28/2010

DOE Weatherization Assistant Version 8.5.0

Page 4 of 5

Measure 6 Practice Lead Sake Weatherization			Components					Inspected	
(Comment				•				
					Estimated			Actual	-
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Material	Each	1					
2	Labor	Labor	Hour						
(Other Detail								
L						Who middle him a reason to the second			
[AT -MANUFACTURE AND ADDRESS OF					Table day of	
			Measure	Sub Total:		S	ub Total:		
	Field Notes:	The second secon			i ma	a and an angle of the second o		i.	
i		Tr. amount	Work Ord	der Grar	nd Total:		Grand	Total:	

Report Run On: 5/28/2010

Page 5 of 5